	UNIFORM HAZARDOUS 1. Generator's US EP/WASTE MANIFEST W A D 9 8 0	AID No. 7 <b>1385</b> 46	Manifest Documer 9 2 0	nt No.	2. F	Page 1				e shaded areas y Federal law.	
3.	3. Generator's Name and Mailing Address ALASKAN COPPER AND BRASS COMPANY					A. State Manifest Document Number					
4.	628 S. Hanford Street Seattle, WA 98134 Generator's Phone ( 206) 623-5801					B. State Generator's ID					
	5. Transporter 1 Company Name 6. US EPA ID Number					C. State Transporter's ID					
7.	CKC, INC. CA Transporter 2 Company Name 8.	US EPA ID N	The state of the s	10	D. I	ranspo tate Tr	orter's I	Phone_ rter's ID	408	)477-2 <del>69</del>	
	and the property of the state of				1,011-01-11-		orter's F	are morning conference			
9.	Designated Facility Name and Site Address Wor Id Resources Company 8113 West Sherman Street	US EPA ID N	lumber				acility's				
		Z <sub>1</sub> D <sub>1</sub> 9 <sub>1</sub> 8 <sub>1</sub> 0 <sub>1</sub> 7	in the same of the same of	The second lines	20000000	acility (60	\$ Phon 2 2	3-91	66		
11.	11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)			12. Containers No. Type		13. Total Quantity		14 Ur Wt/	rit !	I. Waste No.	
a.	RQ. HAZARDOUS WASTE SOLID, N.O. ORM-E, NA9189 (FOO6)	,S.	O <sub>I</sub>	017	в <sub>І</sub> х	1110	07	19	P	F006	
b.		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			<b> </b>	-   	<del>                                     </del>				
c.											
d.		No. of		ı		1	1 1	1			
						or Wildows Specials	01			en e	
15.	Special Handling Instructions and Additional Information  *** 24 HOUR EMERGENCY RES  WEAR	SPONSE: 1- GOGGLES AI				00 C	HEM	TRE	С *	**	
16	GENERATOR'S CERTIFICATION: I hereby declare that the contents of this coproper shipping name and are classified, packed, marked, and labeled, and are according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place economically practicable and that I have selected the practicable method future threat to human health and the environment; OR, if I am a small q the best waste management method that is available to me and that I can affor	e in all respects in pro e to reduce the volum of treatment, storage quantity generator, I h	oper condition ne and toxione, or dispos	in for tra	ansport i waste ge ently av	by highv enerated ailable	d to the	which mi	nimizes	s the present and	
_	Printed/Typed Name	Signature	9,9	2		>			2	onth Day Year 22552	
17.	Printed/Typed Name  Printed/Typed Name  Printed/Typed Name	Signature	en.	'n.	. 1	w			Mo	onth Day Year	
18.	Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name	Signature			10				Мо	onth Day Year	
19.	Discrepancy Indication Space								100 mg		
20.	Facility Owner or Operator: Certification of receipt of hazardous	<del></del>	d by this i	manife	st exce	ept as	noted	in Item		nth Day V	
	Printed/Typed Name Sowaco L. Silvaco	Signature	W			de la				onth Day Year	

Style CF17-6 Printed by LABELMASTER, Div. of AMERICAN LABELMARK CO., CHICAGO, IL 60646 (800)621-5808

EPA Form 8700-22 (Rev. 9-88) Previous editions are obsolete.

NoA	s Kai	J	W(	8113	SOURCES COMPANY W. Sherman St. mix, AZ 85043	
64 680	Gross	Load of		FC	X4	
55 080	Tare	Priver Off		Date	3-02	19 92
9400	_ Net		20.386	rom Common or	1.0	

# WORLD RESOURCES COMPANY

8113 WEST SHERMAN STREET / PHOENIX, ARIZONA 85043 / (602) 233-9166

MAR 0 5 1992

Mr Greg Speers Alaskan Copper & Brass Co 628 South Hanford Street Seattle WA 98134

Dear Greg:

Enclosed is the appropriate copy of the Uniform Hazardous Waste Manifest and the weigh ticket resulting from the transfer of recyclable materials by your company to World Resources Company (WRC) and the transportation of these recyclable materials to the WRC Recycling Facility in Arizona for the purpose of recovering the metal values therein.

Sincerely,

WORLD RESOURCES COMPANY

R Piergalline

Manifest Coordinator

Enclosures

Recycled Pape

print or type. (Form designed for use on elite (12-pitch) typewriter.)			Form A	pproved. OMB N	lo. 2050-0039. Expires 9-30-	
UNIFORM HAZARDOUS  1. Generator's US EPA ID No.  WASTE MANIFEST  1. Generator's US EPA ID No.  Manifest  Document No. \ W A D 9 8 9 7 3 8 5 4 6 7 2 0 0 \			2. Page 1 Information in the shaded are is not required by Federal law			
3. Generator's Name and Mailing Address ALASKAN COPPER AND BRASS 628 S. Hanford Street Seattle 4. Generator's Phone ( 206) 623-5801	COMPANY , WA 98134		A. State Ma B. State Ge	nitest Docum nerator's ID	gent Number	
5. Transporter 1 Company Name	6. USEPAID Numb	4510	MORPHINE THE STREET STREET, AND A PROPERTY OF THE PROPERTY OF	ters Elioney	ACHDY VATVE S	
7. Transporter 2 Company Name	8. US EPA ID Numb	per	E. State Fre F. Transpor	nspeiters le ters Phone		
9. Designated Facility Name and Site Address pany 8113 West Sherman Street Phoenix, Arizona 85043	10. US EPA ID Numb		G. State Fa	olity's ID. <b>51935-9</b> 1	68	
11. US DOT Description (Including Proper Shipping Name, Haz	ard Class and ID Number)	12. Contai	T	i3. 14 otal Ur antity Wt/	1. nit Waste No. Vol	
RQ. HAZARDOUS WASTE SOLID, ORM-E, NA9189 (FOO6)	N.O.S.	0017			P F006	
<b>b.</b>						
c.						
	melt o managi terrori unim <b>as</b> e per minusco cipatiba y con construito de la la graza di manessir si successir de					
of the second of	econited the visit of					
J. Additional Descriptions for Materials Listed Above 1 leaders distributed in the control of th	RESPONSE: 1-(8	00) 424-				
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of	EAR GOGGLES AND		ed above by			
proper shipping name and are classified, packed, marked, and labeled, according to applicable international and national government regulation if I am a large quantity generator, I certify that I have a program in economically practicable and that I have selected the practicable future threat to human health and the environment; OR, if I am a sthe best waste management method that is available to me and that I or	and are in all respects in proper of its.  In place to reduce the volume all the storage, or its and and an armonic field in the storage.	condition for tran nd toxicity of wa disposal curre	nsport by highwa aste generated ntly available to	to the degree o me which mi	nimizes the present and	
Printed/Typed Name GERA L. Thompson	Signature	· Al			Month Day Year	
17. Transporter 1 Acknowledgement of Receipt of Materials						
Denvis Pompey	Signature	mi	pur	<b>.</b>	Month Day Year	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name	Signature				Month Day Year	
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of haza		this manifes	t except as n	oted in Item	The state of the s	
Printed/Typed Name	Signature				Month Day Year	
tyle CF17-6 Printed by LABELMASTER, Div. of AMERICAN LABELMARK CO., CH	ICACO II EDGAE (900)631 5909					

# NOTICE

TO:	8113 V	Resources Co Vest Shermar ix, Arizona 85	n Street						
FROM:			(Company Name)						
	-		(Address)						
SUBJECT:	Land D	Land Disposal Restriction Notice							
Manifest Nur	nber:								
Date of Ship	ment:	All second and a second a second and a second a second and a second a second and a second and a second and a	Name of the Control o						
§3004(d). Th		and Disposal		ation is provided i	§268.32 or RCRA n accordance with				
EPA Material Number	Regulated Constituent	Subcategory	Treatability Group	Treatment Standards  CFR Reference   Prohibition Level					
F006	n/n	N/A	Nonwastewater	40 CFR \$268.41 40 CFR \$268.43					
		:	-						
NOTE: See attac	ched sheet for ins	structions.							
i.									

## MSDS-1

## **Material Safety Data Sheet**

Recycler's Facility Name and Site Address:

### World Resources Company

8113 West Sherman Street Phoenix, Arizona 85043

Telephone Number: 1-602-233-9166

Issued: 8/7/90 Revised: 2/6/91

Call CHEMTREC only in the event of emergencies during shipping that involve a spill, leak, fire, or accident

For Emergencies During Shipping Call: CHEMTREC Day or Night 800-424-9300 Outside Continental U.S. Call:

202-483-7616 Collect All calls are recorded.

Toxicology: (rat, oral)

### Section 1

Generic Name: Electroplating/Metal-Finishing Wastewater Treatment Sludge Environmental Protection Agency (EPA) Waste Classification: F006

Chemical Family: Metallic (Hydroxide) Precipitates

Synonym: Non-ferrous Metal Hydroxide Filter Cake

### PRODUCT - MATERIAL IDENTIFICATION

DOT Shipping Name: Hazardous Waste Solid, N.O.S.

**DOT Hazard Class: ORM-E** 

**DOT Identification Number:** NA-9189

**DOT Emergency Response Guide 31 Applies** 

### <u>HAZARDOUS INGREDIENTS</u> Section 2 Ingredient: **CAS Number:** Content %: **ACGIH-TLV**

Copper Hydroxide 7440-50-8 0-30 Nickel Hydroxide 7440-02-0 0-15 Calcium Hydroxide 1305-62-0 0-15 Diatomaceous Earth 68855-54-9 0-10

1,000 mg/kg 1.0 mg/m3 (Dust) LD-50 1,500 mg/kg 1.0 mg/m3 (Dust) LD-50 5.0 mg/mg (Dust) LD-50 7,340 mg/kg 6.0 mg/mg (Dust) LD-50 3,160 mg/kg PHYSICAL AND REACTIVITY DATA

### Section 3

Description: Solid, Clay-like Clumps,

Gray/Green to Brown, Water Content 30-80%

Specific Gravity: 1 to 1.4 Solubility: Insoluble in water Density: 64 to 90 lbs/cu/ft

Incompatible Reactivity: None Known Vapor Pressure: Insignificant

Stability: Avoid contact with acids Polymerization: Will not occur

Boiling Point: Above 2600°C Melting Point: Above 1800°C

pH: 7.0 to 10.0 Odor: Nil

### Section 4

Flashpoint: Nonflammable Oxidation: Non-oxidizing Special Firefighting Procedures: None Explosive: Non-explosive

Product Decomposition. . . . . (Due to Fire or Explosion): None

**NFPA** Fire Diamond



Listed Carcinogen component: Nickel

Toxicology: See Sec. 2 (Nickel Hydroxide)

Route of Entry: Inhalation and Ingestion

### Section 6

HEALTH EFFECTS AND FIRST AID Inhalation: Dust may irritate mucous membranes and upper respiratory tract. Remove to fresh air and treat symptoms.

Ingestion: Rare in industry. Induce vomiting (do not induce vomiting or give a liquid to an unconcious person) and call a physician.

Eyes: Dust may irritate eyes. Wash with copious amounts of water for 15 minutes, if effects persist, call a physician.

Skin: Dust may irritate skin, causing forms of eczema. Wash with soap and water.

Long-Term Effects: Chronic overexposure may affect the following target organs or body systems-blood, digestive, respiratory, lungs, liver,

Comments: Special attention should be given to employees with anemia, restricted respiratory abilities, lung cancer, permanent kidney damage and metal-sensitive skin or skin lesions.

### Section 7

Handling: Good personal and industrial hygiene should always be practiced. It is recommended that personal protective equipment be used by personnel who will come in contact with the material. The equipment should include eye protection, respirator and

Storage: Keep covered and avoid conditions where wind could cause dispersal. Do not eat, drink or smoke where material is handled to avoid inhalation or ingestion. Store in a dry area under cover from rain.

Spills: Cleaning procedures should not create excessive dust. Vacuum when possible. Package material and send to World Resources Company at above address.

### Respiratory Protection: NIOSH-MSHA approved respirators as required. Other Protective Equipment: Coveralls are recommended, but not required.

### CONTROL MEASURES

Eye Protection: Safety Glasses recommended. Hand Protection: Gloves recommended.

### GENERATORS VERIFICATION

This MSDS is provided solely for informational purposes and no warranty or responsibility is extended even though reasonable precautions have been taken in the preparation of the data contained for this recyclable material. To the best of my knowledge this MSDS describes the recyclable material listed on the attached Manifest Number: \_ Telephone:\_ Date: Company Name and Address:

Signature: